M4 G2 CABLE DRAWINGS
STEP: 3

Machine with Leg Press use A-5 instead of A-4

Part Number	Description	Qty
A-4	Weight Stack to Lat Pull Cable	1